



Model WC5WA4020U specification

The high pressure pump: model WIP5

Pump type: dual plunger reciprocal intensifier. 20:1 intensifier ratio Max pressure: 60,000psi (400Mpa). Continuously adjustable cutting pressure. Max water flow rate: 0.8Gal/min (3.2L/min). High pressure water attenuator to dampen cutting pressure fluctuations. Reliable electronic shift Intensifier driven by: hydraulic pump. Hydraulic pump type: Axial piston hydraulic pump. Hydraulic filtration in oil path with filter cartridge 50HP high efficiency motor with Wye Delta soft start Cooling method: air fan cooling with high efficiency heat exchanger. Use of electric chiller is optional with additional cost. Water filter: 2 stage filtration included inside the pump unit. Integrated Control panel with heavy gauge metal framework CE/CSA/UL certified Electronic components All stainless fittings and tubing Power source: 3 phase, 220/380/415/440VAC, 50/60Hz 37kw, 50HP. Approximate form size: 1600 x900 x1400mm, weight 1100kg.

Protective automatic shut off under the following circumstances:

- Over pressure limit.
- Over temperature limit. •

CNC cutting table: Model CAT4020U

The table consists of water tank, X-Y motion system, Z axis motion, cutting head assembly, and abrasive mini-hopper with adjustable abrasive feeding control. Style: cantilever, water tank is made of stainless steel. Effective cutting area: 2000x4000mm. Maximum Z-axis travel: 6" (150mm) X-Y axis motion system: ball screw, linear motion guide X-Y axis motion drive: AC servo motor Z axis motion: AC motor with speed reducer. X-Y position accuracy is $\pm -0.0015''(0.04mm)$. X-Y axis position repeatability: +/- 0.0004"(0.01mm). Best cutting tolerance: +/- 0.006" (0.15mm). Maximum X-Y axis travel speed: 32ft/min (10m/min). This machine can cut all kinds of metal, marble, granite, glass, ceramic tile, rubber, plastic, virtually any materials.





Mini hopper for abrasive feeding:

Large size to enable long working time without floor size abrasive hopper. Clear window view for easy monitoring. Abrasive valve attachment for easy abrasive on/off control and abrasive flow rate adjustment.

Cutting head assembly:

The assembly consists of pneumatically operated on/off valve and selfaligned cutting head. Maximum Abrasive flow rate: 0.5kg/min (1pound/min). Compressed air source is necessary. An air compressor is optional item from manufacturer. As an option, the cutting head can manually tilt in both x and y directions.

UHP tubing and plumbing kit for connection:

1/4" or 7mm OD UHP tubing from intensifier to cutting head mounted on cutting table Stainless fittings. Rack kit to supporting installation of the tubing.

CNC controller:

CNC controller consists of advanced industrial grade computer and specialized software running on the Microsoft windows platform. The controller is capable of simultaneous X-Y axis interpolation movement. Fast accelerate or decelerate motion and high speed travel from point to point. Simulation without motion or dry run with axis motion but no jetting of water/abrasive are features included. Error stop and trace repeat are also very useful features. Out of range warning and hard stop to prevent damage capability are embedded in the system. Emergency shut off switch is provided. Remote control is provided to control the motion of X-Y-Z axis when operator is away from the controller tower.

DXF file compatibility:

The controller is compatible to dxf file format. Users can save design drawing in .dxf from AutoCAD and read the file into the controller. Controller will post the dxf file to G-code. The controller can also read G-code generated from other CAM software. Controller software interface is based on Microsoft Windows XP/WIN7.

Advanced CAD/CAM software (optional): for design drawing, automatically generating machine path, lead in/out, nesting, tool offset, and generate G code. Features are similar to AutoCAD, and with rich features of CAM.


Email: info@iwmwaterjet.com














Controller screen:

Normal (0) Post (V) Track (E) Prog (R) Info (1) Setting (V) axis vorkcoor machine axis vorkcoor machine x 23.910 23.9 Y 0.000 0.00 Feedspeed F(actual/setting): 0/1200 Current Tool No.: 1 Current Tool No.: 1 Current Tool No.: 1 Feedspeed F(actual/setting): 0/1200 Current Tool No.: 1 Current Tool No.: 1 Current Tool No.: 1 Feedspeed F(actual/setting): 0/1200 Current Tool No.: 1 Current Tool No.: 1 Current Tool No.: 1 Feedspeed F(actual/setting): 0/1200 Current Tool No.: 1 Current Tool No.: 1 Current Tool No.: 1 Feedspeed F(actual/setting): 0/1200 Current Tool No.: 1 Current Tool No.: 1 Current Tool No.: 1 Feedspeed F(actual/setting): 0/1200 Current Tool No.: 1 Current Tool No.: 1 Feedspeed F(actual/setting): 0/1200 Current Tool No.: 1	Ormal (0) Pos (V) Track (2) Prog (8) Info (1) Setting (Y) axis Vorkcoor machadom average 100 mm	POSCID	OFFSET(2)	PROG(3)	SYS(4)	PARAM(5)	DIAG(6)	AUTO (7)	MANUAL (8)	REFER (9)
Window	Image: State of the state		and the second se	1.1220 July 210	and the second se					machcoor
Y 0,000 0.00 Y 0,000 0.00 Feedspeed F(actual/setting): 0'1200 Current Tool No.: 1 Current Tool No.: 1 Current Tool No.: 1 Current Tool No.: 1 Current Tool No.: 1 Statistics S. C. (N) Image: Control of the statistics Image: Control of the statistics Current Tool No.: 1 Image: Control of the statistics Current Tool No.: 1 Image: Control of the statistics Current Tool No.: 1 Image: Control of the statistics Current Tool No.: 1 Image: Control of the statistics Current Tool No.: 1 Image: Control of the statistics Current Tool No.: 1 Image: Control of the statistics Current Tool No.: 1 Image: Control of the statistics Current Tool No.: 1 Image: Control of the statistics Current Tool No.: 1 Image: Control of the statistics Current Tool No.: 1 Image: Control of the statistics Current Tool No.: 1 Image: Control of the statistics Current Tool No.: 1 Image: Control of the statistics Current Tool No.: 1 Image: Control of the statistics Current Tool No.: 1 Image: Control of the statis <td>Y 0.000 0.000 Feedspeed F(actual/setting): 0/1200 Current Tool No.: 1 Cur. File: 5.d.d Feedpaced F(actual/setting): 0/1200 S C. (N) Image: State in the s</td> <td></td> <td>and the state of t</td> <td></td> <td></td> <td>and the second se</td> <td>Contraction of the local division of the loc</td> <td></td> <td></td> <td></td>	Y 0.000 0.000 Feedspeed F(actual/setting): 0/1200 Current Tool No.: 1 Cur. File: 5.d.d Feedpaced F(actual/setting): 0/1200 S C. (N) Image: State in the s		and the state of t			and the second se	Contraction of the local division of the loc			
Current Tool No.: 1 (1000) Current Tool No.: 1 (1000) Current Tool No.: 1 (1000) (1000) (1000) (1000) (1000) (1000) (1000) (1000) (1000) (1000) (1000) (1000)	Current Tool No.: 1 Current T	6								
Current Tool No.: 1 (1000) Current Tool No.: 1 (1000) Current Tool No.: 1 (1000) (1000) (1000) (1000) (1000) (1000) (1000) (1000) (1000) (1000) (1000) (1000)	Current Tool No.: 1 Current T							Feedspee	d F(actual/setting): 0	/ 1200
Image: Contract (B) Image: Contract (B) Image: Contre Image: Contract (B)	Image: Control of the second secon	ō -	0							
Calify and the set of th	Image: Control of the second secon	4 -			~					
Calify and the set of th	Image: Control of the second secon									
Example 1 Feedrate (B) Image: Burtont: 5 Image: Burtont: 5 Image: Burtont: 5 Image: Burtont: 5 <tr< td=""><td>Image: Control of the set of the se</td><td></td><td></td><td></td><td>0</td><td></td><td></td><td>Cur. File: 5.d</td><td>đ</td><td></td></tr<>	Image: Control of the set of the se				0			Cur. File: 5.d	đ	
(1885) US (1885) US	(1889) US (1889) US S. C. (N) 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	-	1 7/					22 2 23		11111
Control Control	Control Contro Control Control	201	V	2				Feedrate	e (B)	
S. C. (N) S.	Contract S. C. (N) Image: Second S							(100%)	0%	1
S. C. (N) S. S. S. (N) S. S. (N) S. S.	S. C. (N) (10000) Burtest: 5 Coll Cross Coll Cross									
Image: state of the state	Image: second	0						S. C. (N)	1.1.1.1.1	1.1.1.1.1
Burtratt Burtratt Burtratt B Burtratt B B B C1 C1 C1 C1 C1 C1 C1	Construction Construction				10/					
0 <td>Bartet: Bortet: Image: Constant of the second of the</td> <td>1</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td>(Lanse)</td> <td>0.9</td> <td></td>	Bartet: Bortet: Image: Constant of the second of the	1						(Lanse)	0.9	
0 <td>Bartet: Bortet: Image: Constant of the second of the</td> <td>0</td> <td></td> <td></td> <td>V</td> <td></td> <td></td> <td></td> <td>1 I I</td> <td>1</td>	Bartet: Bortet: Image: Constant of the second of the	0			V				1 I I	1
3. Herroy, 44/4024 C01 Coll C01 Coll C01 CTO 680 Coll C01 Str. 0500 Pr. 5.4495 Coll C1 311, 4233 Pr. 3.2650 Coll Coll <td>Bready div/UCM Call Boother HL HP GB 517 680 GB 35, 0508 Y=5, 5495 GD GD Image: Color of the color of t</td> <td>20</td> <td></td> <td></td> <td></td> <td>Shartrat: 5</td> <td>5</td> <td>G00F.R.</td> <td>(M)</td> <td></td>	Bready div/UCM Call Boother HL HP GB 517 680 GB 35, 0508 Y=5, 5495 GD GD Image: Color of the color of t	20				Shartrat: 5	5	G00F.R.	(M)	
C21 Boother HL 698 617 688 61 21.6580 Y-5.5495 0 0 0 61 311.4233 Y-5.2659 63 312.8629 Y-11.7916 855.4825 0	C21 Boother HL HP C098 C17 C880 E0 32.6508 9*5.5495 E1 28.0808 E1	2 8						(100%)	GOD Feedrate	1
C01 617 C88 C1 26.0500 F-75.549/5 C0 26.0500 F-75.549/5 C2 - 2 C1 26.0500 F-75.549/5 C0 26.050 F-75.549/5 C1 211.0230 F-75.2650 Cutling C1 211.0230 F-75.2650 Cutling C1 211.0450 F-75.2650 Cutling Cutling Abresive Cutling Abresive	C98 E17 C88 C8 35. IIS 08 Y-5. S495 C8 35. IIS 08 Y-5. S495 C1 28. IIS 08 Y-5. S495 C1 28. IIS 08 Y-5. S495 Calling C1 28. IIS 08 Y-10. S465 812. 7136 Calling C3 312. 4628 Y-11. 7976 Calling C3 315. 4239 Y-17. 74698 82. 1415 Calling									
ci 20.0000 ci 21.0000 ci 21.0000 ci 21.2500 ci 21.28620 ci 21.28620 ci 21.28620	ci 20, 0000 ci 21, 0000 ci 31, 4/33 ¥-3, 2450 ci 31, 4/33 ¥-3, 2450 ci 312, 8620 ¥-11, 7916 855, 4/025 ci 312, 8620 ¥-11, 7916 855, 4/025 ci 315, 6/323 ¥-17, 4/370 81, 7790 ci 315, 6/323 ¥-17, 7698 82, 1/415		C80					7+		
61 x11.4233 ¥-3.2659 63 x12.8629 ¥-11.7916 855.4825 63 x15.1968 ¥-16.9468 x13.7136 Cutting Abrosive	Cit 111.4233 P-3.2658 G3 X12.4629 P-11.7916 B5.4425 G3 X12.4629 P-11.7916 B5.4425 G3 X15.4733 P-17.4978 B1.7136 G3 X15.4739 P-17.7668 82.1415 Cutling							27	5 5	
si #12.454 711.7718 H35.4442 St 3.7136 7. 9	63 215.45739 9-10.7978 835.4623 63 215.4733 9-17.7666 81.7790 63 215.4733 9-17.7666 82.1415	61 311.4	233 ¥-3.2650						Cutting Abresk	ne l
		63 815.1	996 ¥-16.9466 R13.7136					Z-	· · · · · · · · · · · · · · · · · · ·	
	F2 F3 F4 F5 F6 F7 F8 F9 F10 F11 Pwse							_	->>>>	F



This equipment is highly recommended for large tables, such as 2000x4000mm

- Requires 70psi pneumatic source
- Capacity 40 Gallon.
- Self detecting empty/full status of reservoir and start/stop feeding.
- Model number ADS-04-170.



Accessories included in standard package:

High pressure tubing, Water hose, Electrical cables, 1 pcs nozzle, 2 pcs orifice, 1 tube of blue goop. 1 set of special tools for pump maintenance.

Spare parts kit (optional).